







<p>Date: 25.02.2021 Authorized user: Jonas Schütte Work area: Dry Chemistry Workplace: Room 100.030b</p>	<h1>Safety Instruction</h1> <h2>Film Thickness Measurement</h2> <h3>TohoSpec 3100 T</h3>	<p>WWU Münster Nanofabrication Facility (MNF) Center for Soft Nanoscience (SoN) Busso-Peus-Str. 10 48149 Münster</p>
---	--	--

Range of Application		
Operation Thickness Measurement		
Hazard for People and the environment		
	<ul style="list-style-type: none"> Hot components: danger by burn. Heavy components: danger of bruise and bone fractures or fatal injury. Electrical currents: danger by electric shock 	
Safety Measures and Rules of Behavior		
	<ul style="list-style-type: none"> Operating the machine is only allowed after previous instructions and knowledge of the manual. Adequate personal protective equipment has to be worn. Make use of the occupational health care. <p>In case of any unclear issues contact the responsible person Prof. Pernice.</p>	
Action in Failure		
<ul style="list-style-type: none"> In case of any malfunction or abnormality turn off the machine and secure against starting up and inform your direct supervisor. 		
Action in Accident, First Aid		
	<ul style="list-style-type: none"> Inform appointed first aider. Immediately treat small injuries. Enter data in the accident book. In case of severe injuries call an emergency doctor (phone 112). Inform your superior. 	
Maintenance and Disposal		
<ul style="list-style-type: none"> Maintenance work may only be carried out by qualified and instructed staff. 		

Deutsche Version auf Rückseite!