



WESTFÄLISCHE
WILHELMS-UNIVERSITÄT
MÜNSTER

Rate dependence of glass-transitions in metallic glasses

Submitted by:

Patrick-Axel Zitzke

Matriculation number: 422357

20th September 2016

Master thesis prepared at:

Institute for Materials Physics Münster

Primary reviewer: Prof. Dr. Gerhard Wilde

Secondary reviewer: Dr. Martin Peterlechner

Contents

| | |
|---|-----------|
| 1. Introduction | 1 |
| 2. Theoretical background | 3 |
| 2.1. Metallic glasses | 3 |
| 2.2. Glass-transition | 5 |
| 2.2.1. Glass-transition temperature | 6 |
| 2.2.2. Relaxation | 7 |
| 2.3. Free volume model | 9 |
| 2.4. Models of rate dependencies | 11 |
| 2.4.1. Lasocka's equation | 11 |
| 2.4.2. Activation energy | 11 |
| 2.4.3. Kinetic fragility | 13 |
| 2.4.4. Mode coupling theory | 15 |
| 3. Sample preparation | 16 |
| 3.1. Weighing | 16 |
| 3.2. Pre-alloying | 17 |
| 3.3. Fluxing | 18 |
| 3.4. Melt spinning technique and ingot casting | 18 |
| 4. Characterization techniques | 20 |
| 4.1. Energy dispersive X-ray spectroscopy (EDX) | 20 |
| 4.2. X-ray diffraction (XRD) | 21 |
| 4.3. Differential scanning calorimetry (DSC) | 22 |
| 4.4. Fast-scanning chip calorimetry (FSC) | 23 |
| 4.4.1. Working principal | 24 |
| 4.4.2. Sensor chips | 25 |
| 4.4.3. Sample placement | 25 |
| 4.4.4. Computer-assisted data analysis | 26 |
| 4.4.5. Temperature calibration | 29 |
| 5. Fundamental sample characterizations | 32 |
| 5.1. PdNiP bulk | 33 |
| 5.2. PdNiP ribbon | 34 |
| 5.3. AuCuSiAg ribbon PZ | 35 |

| | |
|--|------------|
| 5.4. AuCuSiAg ribbon JB | 36 |
| 6. Heating rate dependence of different metallic glasses | 37 |
| 6.1. Design of measurements | 37 |
| 6.1.1. Reproducibility | 37 |
| 6.2. Heating rate dependence | 38 |
| 6.3. Activation energy of the glass-transition | 42 |
| 6.4. Activation energy of the crystallization | 44 |
| 6.5. Fragility | 45 |
| 6.6. Discussion: Heating rate dependence of different metallic glasses | 47 |
| 7. Measurements over a broad range of rates | 50 |
| 7.1. Design of measurements | 50 |
| 7.1.1. Determination of the sample masses | 51 |
| 7.2. Heating rate dependence | 51 |
| 7.2.1. Comparison with DSC measurements | 51 |
| 7.2.2. Heating rate dependence of the characteristic temperatures | 54 |
| 7.2.3. Fragility | 59 |
| 7.2.4. Activation energy of the glass-transition | 60 |
| 7.2.5. Activation energy of the crystallization | 63 |
| 7.2.6. Discussion: Heating rate dependence | 64 |
| 7.3. Cooling rate dependence | 69 |
| 7.3.1. Determination of the critical cooling rate | 69 |
| 7.3.2. Cooling rate dependence of the characteristic temperatures | 70 |
| 7.3.3. Activation energy of the crystallization | 75 |
| 7.3.4. Discussion: Cooling rate dependence | 77 |
| 8. Conclusions and Outlook | 79 |
| A. Appendix | 81 |
| A.1. DSC curves without zoom | 81 |
| A.2. MATLAB code of FSC analysis program | 83 |
| A.2.1. Main function fsc_peakfind.m | 83 |
| A.2.2. Function peaksfind_heat.m | 87 |
| A.2.3. Function peaksfind_cool.m | 91 |
| A.2.4. Function halfcp.m | 93 |
| Bibliography | 94 |
| List of figures | 98 |
| List of tables | 101 |

| | |
|--|------------|
| Nomenclature | 102 |
| Danksagung | 106 |
| Declaration of Academic Integrity | 107 |